



Boat Cleaning User Guide/Instructions:

Spray **Cleanmax Boating** directly onto the surface to clean, wait between 30 seconds to 1minute, rub slightly if necessary and rinse. If necessary, repeat the process several times. For optimum results use a micro fiber cloth for wiping.

- **DECK and HULL Gel coat or Painted area:** On dry surface. 10% to 20 % dilution
- **TEAK:** on wet surface, but not water saturated, ideally at dawn. 5 % to 50 % dilution
- **FENDERS:** in a soaking bath. 10% to 15 % dilution
- **INFLATABLE (Hypalon):** On dry surface. 5 % to 25 % dilution
- **SAIL:** on dry surface. 5% to 10 % dilution
- **SPARS:** on dry surface. 10% to 20 % dilution
- **WINDOWS:** On dry surface. 1 % dilution
- **LEATHER-IMITATION LEATHER-FABRIC:** On dry surface. No more than 5% dilution
- **STAINLESS STEEL-BRONZE-ALUMINIUM:** On dry surface. 1 % to 5 % dilution

Cleanmaxsolution Hong Kong Ltd
Website: www.cleanmaxsolution.com
Email: info@cleanmaxsolution.com

*Disclaimer:
Safety information: Keep away from children. Wear adapted personal protection equipment (goggles, gloves, ...) when using cleaning products. Always perform a test on a small area first and check product compatibility with the material before applying on the whole area to be cleaned. Cleanmax Solution HK Ltd can not be held responsible for misuse of the product, direct, indirect damages or consequential damages.*